

Highways Annex A – dated 21 August 2025.

Issue	Date Reported	By Whom	To	Progress
Parish Steward Visits 2025	Next Visits 2025 Sept			Any issues to be reported to KW for Parish Steward's next visit.
West Tockenham, Flooding. C120 Main Village	Update May 2025	DK	WC	M Cook reported Vactor Teams had recently cleaned gulleys and all drains were operational.
Tockenham Wick, Flooding / Road surface degradation.	Update Aug 2025	KW	WC	M Cook indicates this has been passed to the WC Drainage Team for investigation.
Tockenham Corner / Primrose Hill - Flooding Request for review of findings following WC Drainage Team site visit July 2024.				CASE CLOSED NFA
Degrading road surface Greenway / Mermaid Corner C120	Update Aug 2025	KW	WC	M Cook has requested BobCat repair work.
Opposite Field View - No 1 Tockenham. Blocked drain/gully. Road area by sewage plant now breaking up due to constant flow of water. Issue linked to main Village flooding. SEE ABOVE	Sept 23 Updated May 2025	KW	WC	Case No.00125935. Investigation Aug 24 shows fractured pipe. Works carried out 21 st Nov 24. Monitor Autumn Winter 2025.
Flooding – south of Rowley Copse C120. Culvert blasted. Awaiting possible watercourse re-direction work by landowner east side of culvert. NOTE – Concerns exist that this may impact on Tockenham Corner.	Nov 24 Updated 22 nd May 2025.	KW	WC	Advice from WC drainage (D Everett). Any watercourse digging between C120 and C130 would likely result in volume /speed of water approaching Tockenham Corner increasing and making any potential flood worse. Case closed.
Junction with Preston Lane C130. – Mermaid Corner. Continuous flooding.	Update Aug 2025	KW	WC	CCTV Survey of total drainage system. Road surface works Mermaid to Breach Lane following drainage remedial work. Action – Drainage and Highways Teams.
C130 Primrose Hill – Drainage clearance	July 2024	KW	WC	Request for responsibility clarification Aug 2025 on Drainage Team report July 2024
A3102 Tockenham Corner – Culvert/road erosion	Update Aug 2025	KW		CCTV Investigation required by Highways (M Cook) of Culvert and road erosion. High Priority. Action – M Cook reports Culvert clear and road sound. Site to be regularly inspected.
C130 Orchard Lane junction at C120 – Road surface degradation.	May 2025. Update Aug 2025.	KW	WC	M Cook has requested repairs and added to Highways Maintenance Programme.