

Tockenham Parish Council RoWs Appendix

| Issue | Case # | Date Reported | By Whom | To | Progress |
|---|---------------|----------------------|----------------|-----------|---|
| Trow Lane entrance (Tock Parish) - At entrance to ROW post leaning heavily requires re-insertion into ground. | 00132308 | 11/11/23 | KW | WC | Still being handed over – spoke to WC who are chasing |
| Entrance to Tock 4/10 sign post down and propped up against metal field gate | 00181753 | 7/8/24 | KW | WC | Same as above? |
| Tock 11/10 Handrail insecure and detached from footings | 00133938 | 21/11/23 | KW | WC | Still being handed over – spoke to WC who are chasing |
| LYNE 24/10 (Tock Parish) Bridge repair on brook/stream crossing. Whole structure failure | 00095032 | 14/02/23 | KW | WC | Still being handed over – spoke to WC who are chasing |
| TOCK8 The stile is broken | 00190589 | 11/10/24 | NP | WC | Still being handed over – spoke to WC who are chasing |
| TOCK7 Bridge broken | 00190592 | 11/10/24 | NP | WC | Still being handed over – spoke to WC who are chasing |